


COPY RIGHT & CONFIDENTIAL

[illegible]

1. PARTS SHALL BE ZINC PLATED AS PER SERVICE GRADE NO.2 OF IS:1573-86 & CHROMATE PASSIVATED TO COLOR IRIDESCENT YELLOW.
2. REMOVE ALL SHARP EDGES AND BURRS



BEML LIMITED
NEW FRONTIERS. NEW DREAMS.