

## Bid invitation

### Information

Description:EMN2/REPAIR OF BRICK LINING

Bid invitation number:6300032855

Version: 1

### Bid invitation rules

Bid invitation currency: INR

**Timezone:** UTC+53

**Submission period:** 15.06.2020 15:00:00

**Opening date:** 15.06.2020 15:00:00

**Created On:** 03.06.2020 11:17:42

### Bid invitation text:

- 1) In E- Bidding system - If you need any type of assistance. Please contact on given phone/Email.  
i) Ph No – 080- 22963269 / 22963141 & ii) Email – admin.srm@beml.co.in.
- 2) In Note and Attachments, firm can write their Technical details and other terms & conditions.
- 3) Quotation validity to be given at least 90 Days from the date of tender opening.
- 4) Quoted rate to be given FOR destination basis ( i.e Freight paid basis upto H&P- Division , KGF )
- 5) Kindly note that BEML Standard payment term is 60 Days credit
- 6) LD and risk Purchase clause are applicable and
- 7) Please contact given below email ids for any type of technical clarification.  
i) hmnp@beml.co.in & ii) hn@beml.co.in

Attachments:

Digital Signature

### Bid invitation details

Item	Product Price Condition	Description	Vendor product number	Delivery date/ performance period	Quantity
1		REPAIR OF BRICK LINING			1 AU

### Item long text:

REPAIR OF BRICK LINING FOR WELLMAN EGG

# Bid invitation

Information  
 Description:EMN2/REPAIR OF BRICK LINING  
 Bid invitation number:6300032855  
 Version: 1

Item	Product Price Condition	Description	Vendor product number	Delivery date/ performance period	Quantity
------	-------------------------	-------------	-----------------------	-----------------------------------	----------

Scope of Work:

- 1. Removal of existing Collar Brick lining & damaged Brick Lining.
- 2. Carrying out Repair of existing brick lining as below
  - a. Complete Collar Brick lining # Collar Size: ID: 480 # 490 MM, OD: 1400 # 1500 MM, Height: 165 # 175 MM.
  - b. Repair of Bottom Brick lining (Retort seating portion) only damaged portion without removing other bricks.
  - c. Repair / Covering of cracks of damaged Element Holding Bricks.
- 3. Replacement of damaged ceramic bobbins as per existing design.
- 4. Removal & Fixing of required Heating Elements.
- 5. After Completion of Brick Lining Repair & curing, fixing of Top Collar plate.
- 6. Firm#s scope of supply:
  - a. Thermotex Cement (To withstand 1300 Deg C) - 1 Tin (35 # 40 KG)
  - b. Ceramic Bobbins (To withstand 1300 Deg C) - 100 No#s
  - c. Necessary Tools for carrying out above works have to be arranged by firm.
- 7. BEML Scope: Hot & Cold Bricks.

Note:

- 1. Firm may visit our works & check Wellman EGG to study quantum of work involved.
- 2. Firm has to Lump sum value for both Labour & Material.

Basic Price	INR	_____
SGST - State GST	%	_____
CGST - Central GST	%	_____