

Bid invitation

Information

Description:EMN3/H&P/1050010985/REPAIR OF BLOWER
Bid invitation number:6300036952

Bid invitation rules

Bid invitation currency: INR
Timezone: UTC+53
Submission period: 20.01.2022 17:00:00
Opening date: 20.01.2022 17:00:00
Created On: 10.01.2022 03:59:41

Bid invitation text:

GENERAL TERMS & CONDITIONS:

1. Delivery Terms: FDD/ FOR BEML, KGF.
2. Payment Terms: 60 days receipt & acceptance of item. For MSME , 45 days.credit
3. Micro & small enterprise bidders to indicate Udyog Aadhaar Memorandum number (UAM) and declaration of UAM on CPPP in their bid.
4. Quote should be valid for minimum 60 days from the date of Bid opening. Bids with validity of less than 60 days are liable for rejection.
5. Indicate GSTIN and applicable GST in their bid.
6. Indicate 08 Digit HSN code for the Materials/ 06 Digit SAC code for service
7. Indicate the time requirement for supply the items/Time required for complete the work
8. Indicate warranty applicable for the material
- 9.Indicate complete specification, make, and other connected details in their bid. If not indicated in the bid liable for rejection.
10. L-1 evaluation will be based on landed cost of technically accepted bids.
- 11.Firm has to quote only for the item as per tender specification. If any deviation in technical specification. Beml reserve the right to reject the offer

NOTE:-

- 1).To upload Bid in e- Bidding system - If you need any type of assistance, Please contact Mr. Krishna Mohan (Ph No – 080- 22963269 / 22963141 & Email – admin.srm@beml.co.in).
- 2) Please contact given below mail IDs & Ph.No. for any type of technical clarification.

i) hn@beml.co.in & ii) hmnp@beml.co.in
08153-279555 PH-08153-279315

+++++
Repair of Blower System of Bogie Hearth Low Tempering Furnace

Bid invitation

Information

Description:EMN3/H&P/1050010985/REPAIR OF BLOWER
 Bid invitation number:6300036952

Scope of Work:

- 1. Removal of existing POP of the Blower Duct
- 2. Removal of Blower Duct Cover
- 3. Removal of Motor Shaft with Fan Impeller
- 4. Dismantling of damaged Impeller Fan
- 5. Manufacturing & Supply of New SS304 Impeller Fan as per existing Fan Impeller
- 6. Proper Balancing of Impeller Fan and matching to our requirement.
- 7. Servicing of Blower Drive Mechanism (Plumber Block Bearings & Shaft Repair)
- 8. Installation of New Impeller & Drive Mechanism
- 9. Fixing of Blower Duct Cover
- 10. Covering of Blower Duct with Ceramic & POP Insulation
- 11. Performance Prove out of Blower Mechanism with minimum vibration & noise.

Scope of Supply:

- 1. New SS 304 Impeller Fan as per existing Fan dimensions
- 2. Ceramic Insulation & POP Material

Note:

- 1. Firm may visit our works before submitting their Offer
- 2. Firm has to remove existing damaged Impeller and Manufacture as per Sample.
- 3. Firm may take the removed Impeller as sample for manufacturing of New one.
- 4. Transportation of sample Impeller & New Impeller is under firm's scope.

Bid invitation details

Item	Product Price Condition	Description	Vendor product number	Delivery date/ performance period	Quantity
1		REPAIR OF BLOWER SYSTEMS BOGIE LOW TEMP			1 AU
	IGST -Integrated GST		%	_____	
	Basic Price		INR	_____	
	CGST - Central GST		%	_____	
	SGST - State GST		%	_____	
	UTGST		%	_____	